



•8786 Sonoma Coast Drive, Winter Garden, FL 34787  
(407)614-4572 Office  
(814)243-1927 Cell  
•dkenvironmental@yahoo.com  
www.dk-environmental.com

©2023 DK Environmental & Construction Services, Inc. All rights reserved.

## LEAD-BASED PAINT RISK ASSESSMENT REPORT

**PREPARED FOR THE FOLLOWING PROPERTY:**



948 NE 6th Street  
Ocala, FL 34470

**PERFORMED ON:**  
November 29, 2023

**PERFORMED AND PREPARED BY:**

A handwritten signature in cursive script that reads "Debra Koontz".

Debra Koontz  
Certified Risk Assessor  
LBP-R-1191376-2

## TABLE OF CONTENTS

- I. **Cover Letter**
- II. **Executive Summary**
- III. **Scope of Inspection**
  - A. Building Background
  - B. Preface
  - C. Training
  - D. Equipment
  - E. Inspection Company
  - F. Methods
  - G. Findings
  - H. Conclusions
  - I. Lead Dust/Soil Hazards
  - J. Recommendations and Options
- IV. **Disclosure Responsibility and Disclaimer**
- V. **XRF Results**
- VI. **Drawings/Floor Plans**
- VII. **Property Photographs**
- VIII. **Risk Assessment Forms**
- IX. **License/Certification**
- X. **XRF Performance Characteristic Sheet**
- XI. **Glossary**
- XII. **Laboratory Results**

**Confidentiality Notice:** This Report is intended only for the use of the individual or entity addressed, and may contain information that is privileged, confidential, and exempt from disclosure under applicable law. If you are not the intended recipient or responsible for delivering this report to the intended recipient, you are hereby notified that any dissemination, distribution, or copying of this report, in whole or in part, is prohibited. If you have received this report in error, please notify us immediately. Thank you.



•8786 Sonoma Coast Drive, Winter Garden, FL 34787  
•(407)614-4572 Office  
•(814)243-1927 Cell  
•dkenvironmental@yahoo.com  
•www.dk-environmental.com

---

**December 07, 2023**

Re: Lead-Based Paint Inspection/Risk Assessment Report  
Property Address: **948 NE 6th Street, Ocala, FL 34470**  
Property Owner: **Marietta Stein**  
Phone: **352-355-0828**

Dear Client:

Please find enclosed the lead inspection/risk assessment report for the property located at **948 NE 6th Street, Ocala, FL 34470**. The survey was performed within the current acceptable industry guidelines, Housing and Urban Development (HUD) Guidelines Chapter 7 (revised 1997) and EPA regulations.

DK Environmental & Construction Services, Inc. (DKE) conducted the lead-based paint inspection services at the above-referenced site on **November 29, 2023**.

DKE used an RMD LPA-1 X-Ray Fluorescence (XRF) lead paint analyzer to sample paint for lead. XRF instrument serial #2737 (resourced on April 21, 2021) was used on this job.

Licensed EPA Lead Risk Assessor Debra Koontz (License No. LBP-R-1191376-2, expiration date 09/06/2024) performed the inspection services.

If you have any questions or concerns regarding this report, please feel free to contact us at (407)614-4572.

Sincerely,

A handwritten signature in black ink that reads "Debra Koontz".

Debra Koontz, President  
DK Environmental & Construction Services, Inc.

## II. Executive Summary

DKE was authorized to perform a lead-based paint (LBP) inspection/risk assessment of the property located at **948 NE 6th Street, Ocala, FL 34470**. DKE tested all painted components according to the specifications described in the protocols for Lead Based Paint testing in the Housing and Urban Development (HUD) Guidelines Chapter 7 (revised 1997) and all applicable Federal, State, and Local regulations.

DKE's scope of services involved XRF testing as well as a surface-by-surface visual inspection of all painted surfaces throughout the entire property to determine which lead-based paint surfaces/components are deteriorated (above de minimis level). All accessible, painted building components (that potentially contain lead-based paint) were tested utilizing X-Ray Fluorescence (XRF) Analysis. The data collected is in Appendix V. Wall "A" in each room is the wall where the front entrance door opening is located (or aligned with the street). Going clockwise and facing wall "A", wall "B" will always be to your right, Wall "C" directly to the rear and wall "D" to the left.

DKE tested a total of **one hundred and eighty-two (182) surfaces via XRF analysis and six (6) calibrations. Fourteen (14) were found to contain lead at levels greater than or equal to the regulatory level of 1.0 mg/cm<sup>2</sup>**. These surfaces are identified in Section III: G. This report represents all field data, observations and findings related to the lead inspection performed in the above referenced property. The results, assessments and findings stated in this report are representative of the conditions observed in this property at the time of the inspection services.

This inspection measures lead in both deteriorated and intact paint surfaces. The procedure involved taking readings from representative surfaces throughout the testing area or room. The most common primary analytical method for detecting lead in paint is X-Ray Fluorescence (XRF). The XRF instrument is used because of its demonstrated abilities to accurately determine the amount of lead that is present without disturbing the painted surfaces as well as its high speed and relatively low cost per sample.

Some building components may have been inaccessible at the time of the inspection services, or were not tested because they were covered by other building materials (paneling, tile, siding, etc.). It is possible that painted surfaces may be hidden by these materials. Such surfaces should be assumed to contain lead-based paint, or should be tested by a licensed lead-based paint inspector or risk assessor.

### **III. Scope of Inspection**

#### **A. Building Background**

The property located at **948 NE 6th Street, Ocala, FL 34470** is an approximately **1,761** square feet building (1 unit), built in **1951**. No history of renovations, repairs, or painting was provided to DKE during the inspection services.

#### **B. Preface**

DKE was authorized to perform lead-based paint testing of the above referenced property to determine the possible presence, condition, location and amount of lead-based paint. The testing was conducted on **November 29, 2023** from 8:31am to 10:22am.

#### **C. Training**

All inspectors utilized by DKE have EPA/State licensure and are licensed Lead Risk Assessors who have passed the "HUD Visual Assessment Course". All Lead Risk Assessors utilized by DKE have also been trained in the use, calibration and maintenance of the X-Ray Fluorescence (XRF) equipment they currently use, along with necessary principles of Radiation Safety.

#### **D. Equipment**

An RMD LPA-1 X-Ray Fluorescence (XRF) lead paint analyzer, serial #2737 was used on this job.

#### **E. Inspection Company**

The inspection services were performed by an inspector/risk assessor employed by DK Environmental & Construction Services, Inc., 8786 Sonoma Coast Drive, Winter Garden, FL 34787, telephone number (407)614-4572.

#### **F. Methods**

The calibration of the type of X-Ray Fluorescence (XRF) is done in accordance with the Performance Characteristic Sheet (PCS) for this instrument. These XRF instruments are calibrated using a calibration standard block of known lead content. Three calibration readings are taken before and after each property is tested to insure manufacturer's standards are met. If the inspection is longer than four hours, a set of three calibration readings must be taken before the four hours expires, and then an additional three calibration readings taken at the end of the inspection. If for any reason the instrument is not maintaining a consistent calibration reading within the manufacturer's standards for performance on the calibration block supplied by the manufacturer, manufacturer's recommendations are used to bring the instrument into calibration. If the instrument cannot be brought back into calibration, it is taken off the site and sent back to the manufacturer for repair and/or re-calibration.



**G. Findings**

Property Address: **948 NE 6th Street, Ocala, FL 34470**

DKE tested a total of **one hundred and eighty-two (182) surfaces via XRF analysis and six (6) calibrations. Fourteen (14) were found to contain lead at levels greater than or equal to the regulatory level of 1.0 mg/cm<sup>2</sup> in paint in the surfaces tested:**

**Interior Components**

Read No.	Wall	Structure	Location	Member	Paint Cond	Substrate	Paint Color	Lead (mg/cm <sup>2</sup> )	Mode
Interior Room 013 Bedroom B									
124	D	Window	Lft	Sash	D	Metal	white	1.5	QM
Interior Room 014 Bedroom C									
140	B	Window	Rgt	Casing	D	Metal	white	1.5	QM
141	B	Window	Rgt	Sash	I	Metal	white	1.5	QM

**Exterior Components**

Read No.	Wall	Structure	Location	Member	Paint Cond	Substrate	Paint Color	Lead (mg/cm <sup>2</sup> )	Mode
015 Exterior									
147	A	Window	Rgt	Sash	D	Metal	green	1.7	QM
148	A	Window	Rgt	Sill	I	Concrete	green	3.4	QM
162	C	Fascia	Ctr		D	Wood	green	1.5	QM
164	C	Garage Door	Rgt	Door	D	Wood	green	1.4	QM
163	C	Wall	U Rgt		D	Wood	green	1.7	QM
176	C	Window	Rgt	Casing	D	Metal	green	2.0	QM
184	D	Fascia	Lft		D	Wood	green	3.3	QM
182	D	Wall	U Lft		D	Wood	green	3.7	QM
183	D	Soffit	Ctr		I	Wood	green	2.3	QM
181	D	Window	Rgt	Casing	D	Metal	green	1.9	QM
179	D	Window	Rgt	Sash	D	Metal	green	1.6	QM

## H. Conclusions

The above-listed components were determined to be positive for lead-based paint, as defined by Environmental Protection Agency/Department of Housing and Urban Development (EPA/HUD) as containing lead-in concentrations greater than or equal to 1.0 mg/cm<sup>2</sup>.

When evaluating this report, according to Chapter 7 HUD guidelines it is assumed that if one testing combination (i.e. window, door) is lead-positive in an interior or exterior room equivalent, all other similar testing combinations in those areas are assumed to be lead-positive. The same is true for negative readings. All inaccessible areas are assumed to be lead-positive, even though they were not able to be tested. Inaccessible areas are noted in Section V – XRF Results.

If the lead evaluation results indicate the presence of lead-based paint, the prospective owner may wish to obtain, at *the prospective owner's expense*, additional services of a lead-based paint inspector or risk assessor, certified for the State in which the property is located, to help understand the positive results. This person would review this report and might make additional recommendations about lead hazard control actions. Interpretations and possible actions may vary when only a few readings indicate the presence of lead-based paint.

This inspection was done in accordance with Lead Safe Housing Rule 24 CFR Part 35 subpart J as amended June 21, 2004. The sample results are presented in Appendix V.

The surface conditions ranged from "Intact" to "Deteriorated" at the time of the inspection. Upon completion of lead hazard reduction activities, A clearance examination is required to determine that the lead hazard reduction efforts were performed adequately. "Paint Film Stabilization" means to repair any defect in the substrate, or any defect in a building component, that is causing the paint deterioration, to remove all loose paint and other loose material from the surface to be treated using lead-safe work practices, and to apply a new protective coating of paint.

A Clearance Examination would include a visual evaluation of all surfaces that were determined to be defective during the initial inspection, and collection of dust samples. It should be determined that the deteriorated paint surfaces have been corrected and that no settled dust lead hazards exist in the dwelling or unit. The clearance report must be signed by a certified/licensed Lead Inspector/Risk Assessor.

Painted surfaces found to be intact during the inspection which contain levels of lead greater than or equal to 1.0 mg/cm<sup>2</sup> could create lead hazards if the paint is turned into dust by abrasion, scraping, or sanding. If conditions of intact paint surfaces become destabilized, these conditions will need to be addressed. If any future construction or modernization work is done on the premises, this report should be given to the contractors as well as the tenants.

**I. Lead Dust/Soil Hazards**

The Following is a List of Lead-Dust Hazards Identified During the Risk Assessment:

- No lead-dust hazards were identified during the risk assessment

The Following is a List of Lead-In-Soil Hazards Identified During the Risk Assessment:

- No lead-in-soil hazards were identified during the risk assessment

**J. Recommendations and Options**

Property Address: **948 NE 6th Street, Ocala, FL 34470**

The following LBP recommendations are based on U.S. Department of Housing and Urban Development (HUD) guidelines for the Evaluation and Control of LBP Hazards in Housing with the 1997 revisions, and all State and Local regulations.

According to Chapter 7 HUD guidelines, if one testing combination (i.e. window, door) is positive for lead in an interior or exterior room equivalent, then all other similar testing combinations in those areas are also assumed to be positive for lead. Likewise, the same is true for negative readings.

Some building components may have been inaccessible at the time of the inspection services, or were not tested because they were covered by other building materials (paneling, tile, siding, etc.). It is possible that painted surfaces may be hidden by these materials. Such surfaces should be assumed to contain lead-based paint, or should be tested by a licensed lead-based paint inspector or risk assessor.



## RECOMMENDATIONS

DKE recommends that corrective action is taken for the following components which were found to contain lead at levels greater than or equal to the regulatory level of 1.0 mg/cm<sup>2</sup> and to be in "Deteriorated" condition. (At the request of the client, options are also provided for lead-positive components found to be "Intact" at the time of the inspection services.) Any and all lead abatement activities should be performed by a licensed and insured Lead Abatement Contractor. It is the Lead Abatement Contractor's responsibility to follow all city, state and federal guidelines when performing lead abatement activities. It is also the Lead Abatement Contractor's responsibility to confirm all quantities and conditions:

### Interior Components

Read No.	Wall	Structure	Location	Member	Paint Cond	Substrate	Paint Color	Lead (mg/cm <sup>2</sup> )	Mode
Interior Room 013 Bedroom B									
124	D	Window	Lft	Sash	D	Metal	white	1.5	QM
Interior Room 014 Bedroom C									
140	B	Window	Rgt	Casing	D	Metal	white	1.5	QM

### Exterior Components

Read No.	Wall	Structure	Location	Member	Paint Cond	Substrate	Paint Color	Lead (mg/cm <sup>2</sup> )	Mode
015 Exterior									
147	A	Window	Rgt	Sash	D	Metal	green	1.7	QM
162	C	Fascia	Ctr		D	Wood	green	1.5	QM
164	C	Garage Door	Rgt	Door	D	Wood	green	1.4	QM
163	C	Wall	U Rgt		D	Wood	green	1.7	QM
176	C	Window	Rgt	Casing	D	Metal	green	2.0	QM
184	D	Fascia	Lft		D	Wood	green	3.3	QM
182	D	Wall	U Lft		D	Wood	green	3.7	QM
181	D	Window	Rgt	Casing	D	Metal	green	1.9	QM
179	D	Window	Rgt	Sash	D	Metal	green	1.6	QM

**OPTIONS**

The options offered herein are based upon observations and XRF results taken during the lead-based paint inspection/risk assessment. Estimated pricing for these options are not provided due to construction industry fluctuations. Precise estimates should be obtained from a certified lead-based paint contractor.

**ACCEPTABLE LEAD-BASED PAINT OPTIONS**

("IC" = Interim Controls "LSWP" = Lead-Safe Work Practices)

**Interior Window Components**

Read No.	Wall	Structure	Location	Member	Paint Cond	Substrate	Paint Color	Lead (mg/cm <sup>2</sup> )	Mode
Interior Room 013 Bedroom B									
124	D	Window	Lft	Sash	D	Metal	white	1.5	QM
Interior Room 014 Bedroom C									
140	B	Window	Rgt	Casing	D	Metal	white	1.5	QM
141	B	Window	Rgt	Sash	I	Metal	white	1.5	QM

- Option A. Paint film stabilization of lead-positive components by application of Kilz primer or equivalent over a LSWP prepared surface and 2 top coats of an interior exposure paint following manufacturer's recommendations. Impact/friction control measures should be taken as necessary. (IC)
- Option B. Removal of positive components and replacement with material similar in appearance, composition, and finish using LSWP.
- Option C. Remove lead-based paint from all window components chemically and repaint using LSWP.

**Exterior Window Components**

Read No.	Wall	Structure	Location	Member	Paint Cond	Substrate	Paint Color	Lead (mg/cm <sup>2</sup> )	Mode
015 Exterior									
147	A	Window	Rgt	Sash	D	Metal	green	1.7	QM
148	A	Window	Rgt	Sill	I	Concrete	green	3.4	QM
176	C	Window	Rgt	Casing	D	Metal	green	2.0	QM
181	D	Window	Rgt	Casing	D	Metal	green	1.9	QM
179	D	Window	Rgt	Sash	D	Metal	green	1.6	QM

- Option A. Paint film stabilization of lead-positive components by application of 1 coat of Kilz primer or equivalent over a LSWP prepared surface and 2 top coats of exterior exposure residential paint following manufacturer's recommendations. Impact/friction control measures should be taken as necessary. (IC)

- Option B. Removal and replacement of window and wrapping with metal exterior window components using LSWP.
- Option C. Remove lead-based paint from all window components chemically and repaint using LSWP.

**Exterior Soffit & Fascia**

Read No.	Wall	Structure	Location	Member	Paint Cond	Substrate	Paint Color	Lead (mg/cm <sup>2</sup> )	Mode
015 Exterior									
162	C	Fascia	Ctr		D	Wood	green	1.5	QM
184	D	Fascia	Lft		D	Wood	green	3.3	QM
183	D	Soffit	Ctr		I	Wood	green	2.3	QM

- Option A. Paint film stabilization by application of 1 coat of Kilz primer or equivalent over a LSWP prepared surface and 2 top coats of exterior exposure residential paint following manufacturer's recommendations. Color chosen by owner. (IC)
- Option B. Enclosure of all lead-positive components with vinyl soffit/metal coil stock using LSWP.
- Option C. Encapsulation of lead-positive components by application of LBC (Lead Barrier Compound) using LSWP.
- Option D. Removal of lead-positive components and replacement with material similar in appearance, composition, and finish using LSWP.
- Option E. Remove lead-based paint chemically and repaint using LSWP.

**Exterior Garage Door**

Read No.	Wall	Structure	Location	Member	Paint Cond	Substrate	Paint Color	Lead (mg/cm <sup>2</sup> )	Mode
015 Exterior									
164	C	Garage Door	Rgt	Door	D	Wood	green	1.4	QM

- Option A. Paint film stabilization of lead-positive components by application of 1 coat of Kilz primer or equivalent over a LSWP prepared surface and 2 top coats of exterior exposure residential paint following manufacturer's recommendations. Impact/friction control measures should be taken as necessary. (IC)
- Option B. Removal and replacement of garage door using LSWP.
- Option C. Remove lead-based paint from garage door chemically and repaint using LSWP.

**Exterior Wood Walls**

Read No.	Wall	Structure	Location	Member	Paint Cond	Substrate	Paint Color	Lead (mg/cm <sup>2</sup> )	Mode
015 Exterior									
163	C	Wall	U Rgt		D	Wood	green	1.7	QM
182	D	Wall	U Lft		D	Wood	green	3.7	QM

- Option A. Paint film stabilization of siding by application of 1 coat of Kilz primer or equivalent over a LSWP prepared surface and 2 top coats of exterior exposure residential paint following manufacturer's recommendations. Color chosen by owner. (IC)
- Option B. Enclosure of walls with house wrap and vinyl siding using LSWP.
- Option C. Remove lead-based paint chemically and repaint using LSWP.

**Dust Mitigation and Cleaning of Work Areas**

- Option A. Specialized lead dust cleaning of all window troughs, window sills, and floors in all work areas in preparation for clearance. This includes areas where lead-based paint was identified, as well as general renovation areas.

#### **IV. DISCLOSURE RESPONSIBILITY AND DISCLAIMER**

##### **Disclosure Responsibility**

A copy of this report must be provided to new lessees (tenants) and purchasers of this property under Federal Law (24 CFR part 35 and 40 CFR part 745) before they become obligated under a lease or sales contract. The complete report must also be provided to new purchasers and it must be made available to new tenants. Landlords (lessors) and sellers are also required to distribute an educational pamphlet and include standard warning language in their leases or sales contracts to ensure that parents have the information they need to protect their children from lead-based paint hazards.

##### **Disclaimer**

This is our report of a visual survey, and X-Ray Fluorescence (XRF) analysis of the readily accessible areas of this building and tested components. The presence or absence of lead-based paint or lead-based paint hazards applies only to the tested or assessed surfaces on the date of the field visit. It should be understood that conditions noted within this report were accurate at the time of the inspection services and in no way reflect the conditions at the property after the date of the inspection services. No other environmental concerns were addressed during the inspection services.



**V. XRF Results**

**948 NE 6th Street, Ocala, FL 34470**

Read No.	Wall	Structure	Location	Member	Paint Cond	Substrate	Paint Color	Lead (mg/cm <sup>2</sup> )	Mode
Interior Room 001 Garage									
014	A	Wall	U Ctr		I	Block	white	-0.1	QM
005	A	Window	Ctr	Casing	I	Metal	green	0.5	QM
004	A	Window	Ctr	Sash	I	Metal	green	0.4	QM
009	B	cabinet	Lft		I	Wood	stain	0.2	QM
008	B	Workbench	Ctr		I	Wood	green	0.6	QM
007	B	cabinet	Rgt		I	Wood	green	0.6	QM
015	B	Wall	U Ctr		I	Block	white	0.4	QM
016	C	Wall	U Rgt		I	Block	white	0.1	QM
013	D	Wall	U Ctr		I	Plaster	white	0.4	QM
006	D	Door	Lft	Door	I	Wood	green	-0.2	QM
010	D	Door	Rgt	Door	I	Wood	white	-0.2	QM
011	D	Door	Rgt	Jamb	I	Wood	white	0.5	QM
012	D	Door	Rgt	Threshold	I	Wood	green	0.6	QM
Interior Room 002 Family Rm									
022	A	Ceiling	Ctr		I	Tile	white	0.0	QM
018	B	Door	Ctr	Jamb	I	Wood	stain	0.1	QM
020	C	Baseboard	Ctr		I	Wood	stain	0.1	QM
017	C	Floor	Ctr		I	Wood	stain	0.0	QM
019	C	Window	Ctr	Casing	I	Wood	stain	0.0	QM
021	D	Ceiling	Ctr		I	Plaster	white	-0.2	QM
Interior Room 003 Dining Rm									
023	A	Ceiling	Ctr		I	Plaster	white	0.3	QM
025	B	Floor	Ctr		I	Wood	stain	0.1	QM
026	C	Baseboard	Ctr		I	Wood	stain	0.2	QM
024	D	Chair Rail	Ctr		I	Wood	stain	0.4	QM
Interior Room 004 Living Rm									
034	A	Wall	U Ctr		I	Plaster	white	0.4	QM
039	A	Window	Rgt	Casing	D	Metal	white	0.2	QM
038	A	Window	Rgt	Sash	I	Metal	white	0.5	QM
037	A	Door	Ctr	Door	I	Wood	white	-0.1	QM
035	B	Wall	U Ctr		I	Plaster	white	-0.1	QM
036	B	Ceiling	Ctr		I	Plaster	white	0.2	QM
029	C	cl shf suppo	Rgt		I	Wood	white	0.4	QM
030	C	closet floor	Rgt		I	Wood	stain	0.4	QM
031	C	closet wall	Rgt		I	Plaster	white	0.0	QM
032	C	Wall	U Ctr		I	Plaster	white	0.0	QM
027	C	Door	Rgt	Door	I	Wood	stain	-0.2	QM
028	C	Door	Rgt	Jamb	I	Wood	white	0.0	QM
033	D	Wall	U Ctr		I	Plaster	white	0.0	QM
040	D	Baseboard	Ctr		I	Wood	white	0.3	QM
Interior Room 005 Hallway									
047	A	Wall	U Ctr		I	Plaster	white	0.0	QM
048	B	Wall	U Ctr		I	Plaster	white	0.0	QM
041	B	Baseboard	Ctr		I	Wood	white	0.4	QM
049	C	Wall	U Ctr		I	Plaster	white	0.2	QM
050	C	Ceiling	Ctr		I	Plaster	white	0.0	QM
044	D	cl shf suppo	Rgt		I	Wood	white	0.0	QM
045	D	closet wall	Rgt		I	Plaster	white	-0.1	QM
046	D	Wall	U Ctr		I	Plaster	white	0.2	QM
042	D	Door	Rgt	Door	I	Wood	stain	0.0	QM
043	D	Door	Rgt	Jamb	I	Wood	white	0.2	QM

Read No.	Wall	Structure	Location	Member	Paint Cond	Substrate	Paint Color	Lead (mg/cm <sup>2</sup> )	Mode
Interior Room 006 Bedroom A									
054	A	Wall	U Ctr		I	Plaster	white	0.1	QM
063	A	Window	Ctr	Sash	D	Metal	white	0.3	QM
056	B	closet wall	Lft		I	Plaster	white	0.1	QM
057	B	cl shf suppo	Lft		I	Wood	white	0.3	QM
060	B	closet floor	Lft		I	Wood	stain	0.4	QM
055	B	Wall	U Ctr		I	Plaster	white	0.2	QM
058	B	Door	Lft	Jamb	I	Wood	white	0.4	QM
059	B	Door	Lft	Door	I	Wood	white	0.1	QM
052	C	Wall	U Ctr		I	Plaster	white	0.0	QM
062	C	Baseboard	Ctr		I	Wood	white	-0.4	QM
051	C	Ceiling	Ctr		I	Plaster	pink	0.0	QM
061	C	Door	Lft	Door	I	Wood	stain	0.2	QM
053	D	Wall	U Ctr		I	Plaster	white	0.3	QM
Interior Room 007 Bathroom									
067	A	Ceiling	Ctr		I	Plaster	white	0.4	QM
068	B	Door	Ctr	Door	I	Wood	stain	-0.2	QM
069	B	Door	Ctr	Jamb	D	Wood	white	0.2	QM
070	C	cabinet	Lft		I	Wood	pink	0.1	QM
066	D	Window	Lft	Casing	D	Metal	white	-0.1	QM
064	D	Window	Lft	Sash	I	Metal	green	0.7	QM
065	D	Window	Lft	Sill	I	Plaster	green	0.4	QM
Interior Room 008 Den									
081	A	Wall	U Ctr		I	Plaster	white	0.3	QM
082	A	Ceiling	Ctr		I	Plaster	white	0.3	QM
072	B	Fireplace	Ctr	Mantle	I	Wood	stain	-0.1	QM
075	B	Crown Mldg	Ctr		I	Wood	white	0.0	QM
078	B	cl shf suppo	Rgt		I	Wood	white	0.0	QM
079	B	closet wall	Rgt		I	Plaster	white	0.4	QM
076	B	Door	Rgt	Jamb	I	Wood	white	0.6	QM
077	B	Door	Rgt	Door	I	Wood	stain	0.0	QM
073	C	Shelf	Ctr		I	Wood	stain	0.1	QM
074	C	Crown Mldg	Ctr		I	Wood	stain	0.0	QM
071	D	Chair Rail	Ctr		I	Wood	stain	0.2	QM
080	D	Wall	U Ctr		I	Plaster	white	0.2	QM
083	D	Window	Ctr	Casing	D	Metal	white	0.0	QM
Interior Room 009 Kitchen									
088	A	cl shf suppo	Ctr		I	Wood	white	0.0	QM
089	A	closet wall	Ctr		I	Plaster	white	0.2	QM
093	A	Wall	U Ctr		I	Plaster	green	0.7	QM
085	A	Baseboard	Ctr		I	Wood	green	0.0	QM
086	A	Door	Ctr	Door	I	Wood	green	-0.1	QM
087	A	Door	Ctr	Jamb	I	Wood	green	0.0	QM
092	B	Wall	U Ctr		I	Plaster	green	0.1	QM
084	C	cabinet	Ctr		I	Wood	green	-0.2	QM
091	C	Wall	U Ctr		I	Plaster	green	0.0	QM
090	D	Ceiling	Lft		D	Plaster	white	0.0	QM
Interior Room 010 Hallway									
094	A	Wall	U Ctr		I	Plaster	yellow	0.0	QM
095	B	Wall	U Ctr		I	Plaster	yellow	0.1	QM
096	C	Wall	U Ctr		I	Plaster	yellow	0.3	QM
100	C	Door	Lft	Jamb	I	Wood	yellow	0.1	QM
101	C	Door	Lft	Door	I	Wood	stain	-0.2	QM
097	D	Wall	U Ctr		I	Plaster	yellow	0.2	QM
099	D	Baseboard	Ctr		I	Wood	yellow	0.2	QM
098	D	Ceiling	Ctr		I	Plaster	white	0.5	QM

Read No.	Wall	Structure	Location	Member	Paint Cond	Substrate	Paint Color	Lead (mg/cm <sup>2</sup> )	Mode
Interior Room 011 Laundry Rm									
105	A	cabinet	Ctr		D	Wood	yellow	0.0	QM
110	A	Wall	U Ctr		I	Plaster	yellow	-0.1	QM
111	B	Wall	U Ctr		I	Plaster	yellow	0.1	QM
102	B	Door	Rgt	Door	I	Wood	stain	-0.2	QM
103	B	Door	Rgt	Jamb	I	Wood	white	0.0	QM
104	C	Shelf	Rgt		I	Wood	white	-0.1	QM
112	C	Wall	U Lft		I	Plaster	yellow	0.0	QM
113	C	Ceiling	Lft		I	Plaster	white	0.0	QM
109	D	Wall	U Ctr		I	Plaster	yellow	-0.1	QM
108	D	Baseboard	Ctr		I	Wood	yellow	0.0	QM
107	D	Floor	Ctr		I	Wood	stain	0.0	QM
106	D	Window	Ctr	Casing	D	Metal	white	0.3	QM
Interior Room 012 Bathroom									
117	B	Door	Lft	Door	I	Wood	stain	0.0	QM
118	B	Door	Lft	Casing	I	Wood	blue	0.2	QM
115	C	cabinet	Lft		I	Wood	blue	0.1	QM
114	C	Ceiling	Lft		D	Plaster	blue	-0.1	QM
116	D	Window	Rgt	Casing	I	Wood	white	0.1	QM
Interior Room 013 Bedroom B									
121	A	closet floor	Lft		I	Wood	stain	-0.2	QM
122	A	closet wall	Lft		I	Wood	stain	-0.2	QM
129	A	Wall	U Ctr		I	Plaster	yellow	0.0	QM
130	A	Ceiling	Ctr		I	Plaster	white	-0.3	QM
119	A	Door	Lft	Jamb	I	Wood	white	-0.1	QM
120	A	Door	Lft	Door	I	Wood	stain	0.0	QM
128	B	Wall	U Ctr		I	Plaster	yellow	-0.2	QM
123	B	Baseboard	Ctr		I	Wood	white	0.0	QM
127	C	Wall	U Ctr		I	Plaster	yellow	0.0	QM
126	D	Wall	U Ctr		I	Plaster	yellow	0.0	QM
125	D	Window	Lft	Casing	D	Metal	green	0.5	QM
124	D	Window	Lft	Sash	D	Metal	white	1.5	QM
Interior Room 014 Bedroom C									
139	A	closet floor	Rgt		I	Wood	stain	0.2	QM
132	A	Wall	U Ctr		I	Plaster	yellow	-0.1	QM
131	A	Ceiling	Ctr		I	Plaster	white	-0.1	QM
137	A	Door	Rgt	Jamb	I	Wood	yellow	-0.1	QM
138	A	Door	Rgt	Door	I	Wood	stain	0.0	QM
135	B	Wall	U Ctr		I	Plaster	yellow	0.3	QM
136	B	Baseboard	Ctr		I	Wood	yellow	0.0	QM
140	B	Window	Rgt	Casing	D	Metal	white	1.5	QM
141	B	Window	Rgt	Sash	I	Metal	white	1.5	QM
134	C	Wall	U Ctr		I	Plaster	yellow	0.3	QM
133	D	Wall	U Ctr		I	Plaster	yellow	-0.2	QM
015 Exterior									
152	A	Fascia	Lft		D	Wood	green	0.1	QM
145	A	Porch Floor	Ctr		I	Concrete	red	0.0	QM
150	A	Porch Ceilin	Ctr		D	Wood	white	0.1	QM
149	A	Wall	L Lft		D	Concrete	white	-0.1	QM
154	A	Wall	U Lft		D	Wood	green	0.1	QM
153	A	Soffit	Lft		D	Wood	green	0.1	QM
151	A	Window	Rgt	Shutter	D	Wood	green	0.6	QM
147	A	Window	Rgt	Sash	D	Metal	green	1.7	QM
148	A	Window	Rgt	Sill	I	Concrete	green	3.4	QM
142	A	Door	Ctr	Door	I	Wood	green	0.1	QM
143	A	Door	Ctr	Jamb	I	Wood	white	0.1	QM
144	A	Door	Ctr	Threshold	I	Concrete	red	0.4	QM
146	A	Railing	Ctr	Railing	D	Metal	green	0.7	QM
156	B	Fascia	Ctr		D	Wood	green	0.3	QM
159	B	Wall	L Ctr		D	Block	white	0.2	QM
155	B	Soffit	Ctr		I	Wood	green	0.0	QM
157	B	Window	Ctr	Sash	D	Metal	green	0.3	QM
158	B	Window	Ctr	Sill	D	Concrete	green	0.0	QM

Read No.	Wall	Structure	Location	Member	Paint Cond	Substrate	Paint Color	Lead (mg/cm <sup>2</sup> )	Mode
015 Exterior									
162	C	Fascia	Ctr		D	Wood	green	1.5	QM
166	C	Screen Door	Ctr	Door	D	Wood	white	0.6	QM
167	C	post	Ctr		I	Wood	white	0.3	QM
168	C	Porch Floor	Ctr		I	Concrete	green	0.0	QM
170	C	Porch Ceilin	Ctr		I	Wood	stain	-0.1	QM
164	C	Garage Door	Rgt	Door	D	Wood	green	1.4	QM
165	C	Garage Door	Rgt	Jamb	D	Wood	white	-0.1	QM
169	C	Wall	P Ctr		I	Block	green	0.2	QM
160	C	Wall	L Rgt		D	Block	white	-0.2	QM
163	C	Wall	U Rgt		D	Wood	green	1.7	QM
161	C	Soffit	Ctr		D	Wood	green	0.5	QM
178	C	Soffit	Ctr		I	Wood	white	0.1	QM
173	C	Window	Ctr	Sill	D	Wood	white	0.6	QM
176	C	Window	Rgt	Casing	D	Metal	green	2.0	QM
177	C	Window	Rgt	Sash	D	Metal	green	0.6	QM
171	C	Door	Ctr	Door	I	Wood	white	0.2	QM
172	C	Door	Ctr	Jamb	D	Wood	white	0.4	QM
174	C	Door	Rgt	Door	I	Wood	green	-0.1	QM
175	C	Door	Rgt	Threshold	I	Wood	green	-0.3	QM
184	D	Fascia	Lft		D	Wood	green	3.3	QM
185	D	Wall	L Ctr		D	Block	white	0.1	QM
182	D	Wall	U Lft		D	Wood	green	3.7	QM
183	D	Soffit	Ctr		I	Wood	green	2.3	QM
181	D	Window	Rgt	Casing	D	Metal	green	1.9	QM
179	D	Window	Rgt	Sash	D	Metal	green	1.6	QM
180	D	Window	Rgt	Sill	I	Concrete	green	0.3	QM

Calibration Readings

001								1.0	TC
002								1.0	TC
003								1.0	TC
186								0.9	TC
187								1.0	TC
188								0.9	TC

---- End of Readings ----




**VI. Drawings/Floor Plans**



DK Environmental & Construction Services, Inc.  
8786 Sonoma Coast Drive, Winter Garden, FL 34787  
407-614-4572 814-243-1927  
dkenvironmental@yahoo.com

### SITE PLAN



Case # 11290831

Address 948 NE 6th St  
Ocala, FL, 34470

**VII. Property Photographs**

**948 NE 6th Street, Ocala, FL 34470**



**Exterior(015) A-Wall**



**Exterior(015) B-Wall**



**Exterior(015) C-Wall**



**Exterior(015) D-Wall**



**Bedroom B(013) D-Wall, Left  
Metal Window Sash  
Lead-Positive, Deteriorated**



**Bedroom C(014) B-Wall, Right  
Metal Window Casing  
Lead-Positive, Deteriorated**





Exterior(015) A-Wall, Right  
Metal Window Sash  
Lead-Positive, Deteriorated



Exterior(015) C-Wall, Center  
Metal Window Casing  
Lead-Positive, Deteriorated



Exterior(015) C-Wall, Right  
Upper Wood Wall  
Lead-Positive, Deteriorated



Exterior(015) C-Wall, Right  
Wood Garage Door  
Lead-Positive, Deteriorated



Exterior(015) C-Wall, Center  
Wood Fascia  
Lead-Positive, Deteriorated



Exterior(015) D-Wall, Left  
Wood Fascia  
Lead-Positive, Deteriorated





Exterior(015) D-Wall, Left  
Upper Wood Wall  
Lead-Positive, Deteriorated



Exterior(015) D-Wall, Right  
Metal Window Sash, Casing  
Lead-Positive, Deteriorated

**VIII. Risk Assessment Forms**

**DK ENVIRONMENTAL & CONSTRUCTION SERVICES, INC.**

8786 Sonoma Coast Drive, Winter Garden, FL, 34787      dkenvironmental@yahoo.com  
 PHONE: (814)243-1927      www.dk-environmental.com

**RESIDENT QUESTIONNAIRE**

Date of Construction 1957

**Children/Children's Habits**

1. (a) Do you have any children that live in your home? Yes \_\_\_\_\_ No  (If no children, skip to Question 5)
- (b) If yes, how many? \_\_\_\_\_ Ages? \_\_\_\_\_
- (c) Record blood lead levels, if known. \_\_\_\_\_

2. Location of the rooms/areas where each child sleeps, eats, and plays.

Name of child	Location of bedroom	Location of all rooms where child eats	Primary location where child plays indoors	Primary location where child plays outdoors

3. Where are toys stored/kept? \_\_\_\_\_
4. Is there any visible evidence of chewed or peeling paint on the woodwork, furniture, or toys? Yes \_\_\_\_\_ No \_\_\_\_\_

**Family Use Patterns**

5. Which entrances are used most frequently? Back Door
6. Which windows are opened most frequently? NO
7. Do you use window air conditioners? If yes, where? NO  
*(Condensation often causes paint deterioration)*
8. (a) Do any household members garden? Yes \_\_\_\_\_ No
- (b) Location of garden \_\_\_\_\_
- (c) Are you planning any landscaping activities that will remove grass or ground covering? Yes \_\_\_\_\_ No
9. (a) How often is the household cleaned? When Needed
- (b) What cleaning methods do you use? General Cleaning
10. (a) Did you recently complete any building renovations? Yes \_\_\_\_\_ No
- (b) If yes, where? \_\_\_\_\_
- (c) Was building debris stored in the yard? If yes, where? \_\_\_\_\_
11. Are you planning any building renovations? If yes, where? NO
12. (a) Do any household members work in a lead-related industry? Yes \_\_\_\_\_ No
- (b) If yes, where are dirty work clothes placed and cleaned? \_\_\_\_\_

Marietta M. Stein  
 Homeowner Signature

11-29-23  
 Date

**DK ENVIRONMENTAL & CONSTRUCTION SERVICES, INC.**

8786 Sonoma Coast Drive, Winter Garden, FL, 34787  
 PHONE: (814)243-1927

dkenvironmental@yahoo.com  
 www.dk-environmental.com

**BUILDING CONDITION FORM**

Property Address 948 NE 6<sup>th</sup> St Ocala, FL, 34470

Date of Risk Assessment 11-29-23

CONDITION	YES	NO
Roof missing parts of surfaces (tiles, boards, shakes, etc.)		/
Roof has holes or large cracks		/
Gutters or downspouts broken		/
Chimney masonry cracked, bricks loose or missing, obviously out of plumb		/
Exterior or interior walls have obvious large cracks or holes, requiring more than routine pointing (if masonry) or painting		/
Exterior siding has missing boards or shingles		/
Water stains on interior walls or ceilings	✓	
Plaster walls or ceilings deteriorated		/
Two or more windows or doors broken, missing, or boarded up		/
Porch or steps have major elements broken, missing, or boarded up		/
Foundation has major cracks, missing material, structure leans, or visibly unsound		/
* TOTAL NUMBER	1	10

\* If the "YES" column has two or more checks, the dwelling is usually considered to be in poor condition for the purposes of a risk assessment. However, specific conditions and extenuating circumstances should be considered before determining the final condition of the dwelling and the appropriateness of a lead hazard screen.

Notes: Shed Not Inspected

**Circle the Answer to each or write in different information:**

- Housekeeping - Poor Fair Good
- Soffit/Fascia - Wrapped Bare
- Exterior Walls - Brick Aluminum Vinyl Wood Other BLOCK
- Type of Structure - Single Family Detached Duplex Apartment

**DK ENVIRONMENTAL & CONSTRUCTION SERVICES, INC.**

8786 Sonoma Coast Drive, Winter Garden, FL, 34787  
 PHONE: (814)243-1927

dkenvironmental@yahoo.com  
 www.dk-environmental.com

**XRF FIELD DATA**

Billing Client: <u>Ocala Community Dev</u>	Date of Inspection/Assessment: <u>11-29-23</u>
Address: <u>201 SE 3rd St, 2nd FL</u> <u>Ocala, FL, 34471</u>	Resident's Name: <u>Marietta Stein</u>
Contact/Phone Number: <u>Shaneka Green</u> <u>352-624-8231</u>	Inspection/Assessment Address: <u>948 NE 6th St</u> <u>Ocala, FL, 34470</u>

Inspector Name/License No: <u>Debra Koontz / LBP-R-I 191376-2</u>
XRF Report No: <u>11290831</u> Number of Readings: <u>188</u>
XRF Serial Number: <u>2737</u> Number of Wipes Collected: <u>8, 1 So. 1</u>

<p><u>Purpose of Inspection/Assessment:</u></p> <input checked="" type="checkbox"/> Owner-Occupied Rehabilitation Program <input type="checkbox"/> First Time Home Buyer Program <input type="checkbox"/> Section 8 Qualification <input type="checkbox"/> Real Estate Transaction <input type="checkbox"/> Commercial/Industrial Compliance <input type="checkbox"/> Personal/Private Request <input type="checkbox"/> Clearance Only <input type="checkbox"/> Renter Rehabilitation <input type="checkbox"/> Landlord Renovation <input type="checkbox"/> Other _____	<p><u>Type of Construction:</u></p> <input type="checkbox"/> Wood Frame <input type="checkbox"/> Brick <input type="checkbox"/> Vinyl Siding <input type="checkbox"/> Aluminum Siding <input checked="" type="checkbox"/> Other: <u>Block</u> Number of Stories: <u>1</u> Number of Rooms: _____ Date of Construction: <u>1951</u> Porches and Location: <u>A, C-walls</u> Yards and Location: <u>All-walls</u> <input type="checkbox"/> Garage ( <input type="checkbox"/> Attached <input type="checkbox"/> Detached )
--	---

Project Notes: \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

**IX. License/Certification**



United States Environmental Protection Agency

This is to certify that



Debra L. Koontz

has fulfilled the requirements of the Toxic Substances Control Act (TSCA) Section 402, and has received certification to conduct lead-based paint activities pursuant to 40 CFR Part 745.226 as

Inspector

In the Jurisdiction of:

All EPA Administered Lead-based Paint Activities Program States, Tribes and Territories

This certification is valid from the date of issuance and expires May 13, 2024

LBP-I191376-1

Certification #

April 29, 2021

Issued On



*Adrienne Prisela*

Adrienne Prisela, Manager, Toxics Office

Land Division

United States Environmental Protection Agency

This is to certify that



Debra L. Koontz

has fulfilled the requirements of the Toxic Substances Control Act (TSCA) Section 402, and has received certification to conduct lead-based paint activities pursuant to 40 CFR Part 745.226 as

Risk Assessor

In the Jurisdiction of:

All EPA Administered Lead-based Paint Activities Program States, Tribes and Territories

This certification is valid from the date of issuance and expires September 06, 2024

LBP-R191376-2

Certification #

August 18, 2021

Issued On



*Adrienne Prisela*

Adrienne Prisela, Manager, Toxics Office

and Division

**X. XRF Performance Characteristics Sheet**

**Performance Characteristic Sheet**

EFFECTIVE DATE: October 24, 2000

EDITION NO.: 4

**MANUFACTURER AND MODEL:**

Make: Radiation Monitoring Devices

Model: LPA-1

Source: <sup>57</sup>Co

Note: This sheet supersedes all previous sheets for the XRF instrument of the make, model, and source shown above for instruments sold or serviced after June 26, 1995. For other instruments, see prior editions.

**FIELD OPERATION GUIDANCE**

**OPERATING PARAMETERS**

Quick mode or nominal 30-second standard mode readings.

**XRF CALIBRATION CHECK LIMITS**

0.7 to 1.3 mg/cm <sup>2</sup> (inclusive)
---

**SUBSTRATE CORRECTION:**

For XRF results below 4.0 mg/cm<sup>2</sup>, substrate correction is recommended for:

Metal using 30-second standard mode readings.

None using quick mode readings.

Substrate correction is not needed for:

Brick, Concrete, Drywall, Plaster, and Wood using 30-second standard mode readings

Brick, Concrete, Drywall, Metal, Plaster, and Wood using quick mode readings

**THRESHOLDS:**

30-SECOND STANDARD MODE READING DESCRIPTION	SUBSTRATE	THRESHOLD (mg/cm <sup>2</sup> )
Results corrected for substrate bias on metal substrate only	Brick	1.0
	Concrete	1.0
	Drywall	1.0
	Metal	0.9
	Plaster	1.0
	Wood	1.0

QUICK MODE READING DESCRIPTION	SUBSTRATE	THRESHOLD (mg/cm <sup>2</sup> )
Readings not corrected for substrate bias on any substrate	Brick	1.0
	Concrete	1.0
	Drywall	1.0
	Metal	1.0
	Plaster	1.0
	Wood	1.0

## BACKGROUND INFORMATION

### EVALUATION DATA SOURCE AND DATE:

This sheet is supplemental information to be used in conjunction with Chapter 7 of the HUD Guidelines for the Evaluation and Control of Lead-Based Paint Hazards in Housing (HUD Guidelines\*). Performance parameters shown on this sheet are calculated from the EPA/HUD evaluation using archived building components. Testing was conducted on approximately 150 test locations in July 1995. The instrument that performed testing in September had a new source installed in June 1995 with 12 mCi initial strength.

### OPERATING PARAMETERS:

Performance parameters shown in this sheet are applicable only when properly operating the instrument using the manufacturer's instructions and procedures described in Chapter 7 of the HUD Guidelines.

### XRF CALIBRATION CHECK:

The calibration of the XRF instrument should be checked using the paint film nearest 1.0 mg/cm<sup>2</sup> in the NIST Standard Reference Material (SRM) used (e.g., for NIST SRM 2579, use the 1.02 mg/cm<sup>2</sup> film).

If readings are outside the acceptable calibration check range, follow the manufacturer's instructions to bring the instruments into control before XRF testing proceeds.

### SUBSTRATE CORRECTION VALUE COMPUTATION

Chapter 7 of the HUD Guidelines provides guidance on correcting XRF results for substrate bias. Supplemental guidance for using the paint film nearest 1.0 mg/cm<sup>2</sup> for substrate correction is provided:

XRF results are corrected for substrate bias by subtracting from each XRF result a correction value determined separately in each house for single-family housing or in each development for multifamily housing, for each substrate. The correction value is an average of XRF readings taken over the NIST SRM paint film nearest to 1.0 mg/cm<sup>2</sup> at test locations that have been scraped bare of their paint covering. Compute the correction values as follows:

Using the same XRF instrument, take three readings on a bare substrate area covered with the NIST SRM paint film nearest 1 mg/cm<sup>2</sup>. Repeat this procedure by taking three more readings on a second bare substrate area of the same substrate covered with the NIST SRM.

Compute the correction value for each substrate type where XRF readings indicate substrate correction is needed by computing the average of all six readings as shown below.

For each substrate type (the 1.02 mg/cm<sup>2</sup> NIST SRM is shown in this example; use the actual lead loading of the NIST SRM used for substrate correction):

$$\text{Correction value} = (1\text{st} + 2\text{nd} + 3\text{rd} + 4\text{th} + 5\text{th} + 6\text{th Reading}) / 6 - 1.02 \text{ mg/cm}^2$$

Repeat this procedure for each substrate requiring substrate correction in the house or housing development.

### EVALUATING THE QUALITY OF XRF TESTING:

Randomly select ten testing combinations for retesting from each house or from two randomly selected units in multifamily housing. Use either 15-second readings or 60-second readings.

Conduct XRF re-testing at the ten testing combinations selected for retesting.

Determine if the XRF testing in the units or house passed or failed the test by applying the steps below.

Compute the Retest Tolerance Limit by the following steps:

Determine XRF results for the original and retest XRF readings. Do not correct the original or retest results for substrate bias. In single-family housing a result is defined as the average of three readings. In multifamily housing, a result is a single reading. Therefore, there will be ten original and ten retest XRF results for each house or for the two selected units.

Calculate the average of the original XRF result and retest XRF result for each testing combination.

Square the average for each testing combination.

Add the ten squared averages together. Call this quantity C.

Multiply the number C by 0.0072. Call this quantity D.

Add the number 0.032 to D. Call this quantity E.

Take the square root of E. Call this quantity F.

Multiply F by 1.645. The result is the Retest Tolerance Limit.

Compute the average of all ten original XRF results.

Compute the average of all ten re-test XRF results.

Find the absolute difference of the two averages.

If the difference is less than the Retest Tolerance Limit, the inspection has passed the retest. If the difference of the overall averages equals or exceeds the Retest Tolerance Limit, this procedure should be repeated with ten new testing combinations. If the difference of the overall averages is equal to or greater than the Retest Tolerance Limit a second time, then the inspection should be considered deficient.

Use of this procedure is estimated to produce a spurious result approximately 1% of the time. That is, results of this procedure will call for further examination when no examination is warranted in approximately 1 out of 100 dwelling units tested.

#### **BIAS AND PRECISION:**

Do not use these bias and precision data to correct for substrate bias. These bias and precision data were computed without substrate correction from samples with reported laboratory results less than 4.0 mg/cm<sup>2</sup> lead. The data which were used to determine the bias and precision estimates given in the table below have the following properties. During the July 1995 testing, there were 15 test locations with a laboratory-reported result equal to or greater than 4.0 mg/cm<sup>2</sup> lead. Of these, one 30-second standard mode reading was less than 1.0 mg/cm<sup>2</sup> and none of the quick mode readings were less than 1.0 mg/cm<sup>2</sup>. The instrument that tested in July is representative of instruments sold or serviced after June 26, 1995. These data are for illustrative purposes only. Actual bias must be determined on the site. Results provided above already account for bias and precision. Bias and precision ranges are provided to show the variability found between machines of the same model.

30-SECOND STANDARD MODE READING MEASURED AT	SUBSTRATE	BIAS (mg/cm <sup>2</sup> )	PRECISION (mg/cm <sup>2</sup> )
0.0 mg/cm <sup>2</sup>	Brick	0.0	0.1
	Concrete	0.0	0.1
	Drywall	0.1	0.1
	Metal	0.3	0.1
	Plaster	0.1	0.1
	Wood	0.0	0.1
0.5 mg/cm <sup>2</sup>	Brick	0.0	0.2
	Concrete	0.0	0.2
	Drywall	0.0	0.2
	Metal	0.2	0.2
	Plaster	0.0	0.2
	Wood	0.0	0.2
1.0 mg/cm <sup>2</sup>	Brick	0.0	0.3
	Concrete	0.0	0.3
	Drywall	0.0	0.3
	Metal	0.2	0.3
	Plaster	0.0	0.3
	Wood	0.0	0.3
2.0 mg/cm <sup>2</sup>	Brick	-0.1	0.4
	Concrete	-0.1	0.4
	Drywall	-0.1	0.4
	Metal	0.1	0.4
	Plaster	-0.1	0.4
	Wood	-0.1	0.4

Precision at 1 standard deviation.

**CLASSIFICATION RESULTS:**

XRF results are classified as positive if they are greater than the upper boundary of the inconclusive range, and negative if they are less than the lower boundary of the inconclusive range, or inconclusive if in between. The inconclusive range includes both its upper and lower bounds. Earlier editions of this *XRF Performance Characteristics Sheet* did not include both bounds of the inconclusive range as "inconclusive." While this edition of the Performance Characteristics Sheet uses a different system, the specific XRF readings that are considered positive, negative, or inconclusive for a given XRF model and substrate remain unchanged, so previous inspection results are not affected.

**DOCUMENTATION:**

An EPA document titled *Methodology for XRF Performance Characteristic Sheets* provides an explanation of the statistical methodology used to construct the data in the sheets, and provides empirical results from using the recommended inconclusive ranges or thresholds for specific XRF instruments. For a copy of this document call the National Lead Information Center Clearinghouse at 1-800-424-LEAD. A HUD document titled *A Nonparametric Method for Estimating the 5th and 95th Percentile Curves of Variable-Time XRF Readings Based on Monotone Regression* provides supplemental information on the methodology for variable-time XRF instruments. A copy of this document can be obtained from the HUD lead web site, [www.hud.gov/lea](http://www.hud.gov/lea).

This edition of the XRF Performance Characteristic Sheet was developed by QuanTech, Inc., under a contract from the U.S. Department of Housing and Urban Development (HUD). HUD has determined that the information provided here is acceptable when used as guidance in conjunction with Chapter 7, Lead-Based Paint Inspection, of HUD's *Guidelines for the Evaluation and Control of Lead-Based Paint Hazards in Housing*.



**XI. Glossary**

**Abatement:** A measure or set of measures designed to permanently eliminate lead-based paint hazards or lead based paint. Abatement strategies include the removal of lead-based paint, enclosure, encapsulation, replacement of building components coated with lead-based paint, removal of lead-contaminated dust, and removal of lead-contaminated soil or overlaying of soil with a durable covering such as asphalt (grass and sod are considered interim control measures). All of these strategies require preparation, cleanup, waste disposal, post-abatement clearance testing, record keeping, and, if applicable, monitoring. See also **Complete Abatement** and **Interim controls**.

**Accreditation:** A formal recognition certifying that an organization, such as a laboratory, is competent to carry out specific tasks or types of tests.

**Accuracy:** The degree of agreement between an observed value and an accepted reference value (a "true" value); a data quality indicator. Accuracy includes a combination of random errors (Precision) and systematic errors (bias) due to sampling and analysis.

**Bare soil:** Soil not covered with grass, sod, some other similar vegetation, or paving, including the sand in sandboxes.

**Building component:** Any element of a building that may be painted or have dust on its surface, e.g. walls, stair treads, floors, railings, doors, windowsills, etc.

**Certification:** The process of testing and evaluating against certain specifications the competence of a person, organization, or other entity in performing a function or service, usually for a specified period of time.

**Certified:** The designation for Contractors who have completed training and other requirements to safely allow them to undertake risk assessments, inspections, or abatement work. Risk assessors, inspectors, and Abatement Contractors should be certified by the appropriate local, State, or Federal agency.

**Chewable surface:** See **Chewed surface**.

**Chewed surface:** Any painted surface that shows evidence of having been chewed or mouthed by a young child. A chewed surface is usually a protruding, horizontal part of a building, such as an interior windowsill.

**Cleaning:** The process of using a vacuum and wet cleaning agents to remove leaded dust. The process includes the removal of bulk debris from the work area. OSHA prohibits the use of compressed air to clean lead-contaminated dust from a surface.

**Clearance examination:** Visual examination and collection of environmental samples by an inspector or risk assessor, or, in some circumstances, a Sampling Technician, and analysis by an accredited laboratory upon completion of an abatement project, interim control intervention, or maintenance job that disturbs lead-based paint (or paint suspected of being lead-based). The clearance examination is performed to ensure that lead exposure levels do not exceed standards established by the EPA Administrator pursuant to Title IV of the Toxic Substances Control Act, and that any cleaning following such work adequately meets those standards.

**Common area:** A room or area that is accessible to all residents in a community (e.g. hallways or lobbies). In general, any area not kept locked.

**Composite sample:** A single sample made up of individual subsamples. Analysis of a composite sample produces the arithmetic mean of all subsamples.

**Containment:** A process to protect workers and the environment by controlling exposures to the lead-contaminated dust and debris created during abatement.

**Deteriorated lead-based paint:** Any lead-based paint coating on a damaged or deteriorated surface or fixture, or any interior or exterior lead-based paint that is peeling, chipping, flaking, worn, chalking, alligating, cracking, or otherwise becoming separated from the substrate.

**Disposal (of waste):** The discharge, deposit, injection, dumping, spilling, leaking, or placement of solid or liquid waste on land or in water so that none of its constituents can pollute the environment by being emitted into the air or discharged into a body of water, including groundwater.

**Encapsulation:** Any covering or coating that acts as a barrier between lead-based paint and the environment, the durability of which relies on adhesion and the integrity of the existing bonds between multiple layers of paint and between the paint and the substrate. See also **Enclosure**.

**Enclosure:** The use of rigid, durable construction materials that are mechanically fastened to the substrate to act as a barrier between the lead-based paint and the environment.

**Evaluation:** Risk assessment, paint inspection, reevaluation, investigation, clearance examination, or risk assessment screen.

**Examination:** See **Clearance Examination**.

**Federal Register (FR):** A daily Federal publication that contains proposed and final regulations, rules, and notices.

**Impact Surface:** An interior or exterior surface (such as surfaces on doors) subject to damage by repeated impact or contact.

**Inspection (of paint):** A surface-by-surface investigation to determine the presence of lead-based paint (in some cases including dust and soil sampling) and a report of the results.

**Interim controls:** A set of measures designed to temporarily reduce human exposure or possible exposure to lead-based paint hazards. Such measures include specialized cleaning, repairs, maintenance, painting, temporary containment, and management and resident education programs. Monitoring, conducted by Owners, and reevaluations, conducted by professionals, are integral elements of interim control. Interim controls include dust removal, paint film stabilization, treatment of friction and impact surfaces, installation of soil coverings such as grass or sod, and land use controls. See also **Monitoring, Reevaluations, and Abatement**.

**Interior windowsill:** The portion of the horizontal window ledge that protrudes into the interior of the room, adjacent to the window sash when the window is closed. Often called the window stool.

**Latex:** A waterborne emulsion paint made with synthetic binders, such as 100% acrylic, vinyl acrylic, terpolymer, or styrene acrylic. A stable emulsion of polymers and pigment in water.

**Lead:** Lead includes metallic lead and inorganic and organic compounds of lead.

**Lead-based paint:** Any paint, varnish, shellac, or other coating that contains lead equal to or greater than 1.0 mg/cm<sup>2</sup> (milligrams of lead per square centimeter of surface) as measured by XRF or laboratory analysis, or 0.5% by weight (5,000ug/g, 5,000 ppm (parts per million), or 5,000 mg/kg) as measured by laboratory analysis (Local definitions may vary.)

**Lead-based paint hazard:** A condition in which exposure to lead from lead-contaminated dust, lead-contaminated soil, or deteriorated lead-based paint would have an adverse effect on human health (as established by the EPA Administrator under Title IV of the Toxic Substances Control Act). Lead-based paint hazards include, for example, deteriorated lead-based paint, leaded dust levels above applicable standards. And bare leaded soil above applicable standards.

**Lead-based paint hazards control:** Activities to control and eliminate lead-based paint hazards, including interim controls, abatement, and complete abatement.

**Lead-contaminated dust:** Surface dust in residences that contains an area concentration of lead in excess of the standard established by the EPA Administrator, pursuant to Title IV of the Toxic Substances Control Act. As of April 01, 2017, EPA standards for lead dust for risk assessments are  $\geq 10$  ug/ft<sup>2</sup> (micrograms of lead per square foot) for floors, and  $\geq 100$  ug/ft<sup>2</sup> for interior windowsills. The EPA standard for clearance are  $< 10$  ug/ft<sup>2</sup> for floors, 100 ug/ft<sup>2</sup> for windowsills, and 100 ug/ft<sup>2</sup> for window troughs. Porch floors are also wiped during final clearance, with a lead dust clearance action level of  $< 40$  ug/ft<sup>2</sup>.

**Lead-contaminated soil:** Bare soil on residential property that contains lead in excess of the standard established by the EPA Administrator, pursuant to Title IV of the Toxic Substances Control Act. The standard is 400 ug/g in play areas and 1,200 ug/g in the rest of the property.

**Leaded dust:** See **Lead-contaminated dust**.

**Licensed:** Holding a valid license or certification issued by the EPA or by an EPA-approved State program pursuant to Title IV of the Toxic Substances Control Act. The license is based on certification for lead-based paint hazard control work. See also **Certified**.

**Maintenance:** Work intended to maintain adequate living conditions in a dwelling, which has the potential to disturb lead-based paint or paint that is suspected of being lead-based.

**Mean:** The arithmetic average of a series of numerical data values. For example, the algebraic sum of the data values divided by the number of data values.

**Microgram (ug):** 1/1,000,000 of a gram. Used to measure weight.

**Monitoring:** Surveillance to determine (1) that known or suspected lead-based paint is not deteriorating, (2) that lead-based paint hazard controls, such as paint stabilization, enclosure, or encapsulation have not failed, and (3) that structural problems do not threaten the integrity of hazard controls.

**Owner:** A person, firm, corporation, guardian, conservator, receiver, trustee, executor, government agency or entity, or other judicial officer who, alone or with others, owns, holds, or controls the freehold or leasehold title or part of the title to property, with or without actually possessing it. This definition includes a vendee who possesses the title, but does not include a mortgagee or an Owner of a reversionary interest under a ground rent lease.

**Paint inspector:** An individual who has completed training from an accredited program and been licensed or certified by the appropriate State or local agency to (1) perform inspections to determine and report the presence of lead-based paint on a surface-by-surface basis through onsite testing, (2) report the findings of such an inspection, (3) collect environmental samples for laboratory analysis, (4) perform clearance testing, and optionally (5) document successful compliance with lead-based paint hazard control requirements or standards.

**Paint removal:** An abatement strategy that entails the removal of lead-based paint from surfaces. For lead hazard control work, this can mean using chemicals, heat guns below 1,100° F, and certain contained abrasive methods. Open-flame burning, open-abrasive blasting, sandblasting, extensive dry scraping, and stripping in a poorly ventilated space using a volatile stripper are prohibited paint removal methods. Hydroblasting is not recommended.

**Plastic:** See **Polyethylene plastic**.

**Polyethylene plastic:** All references to polyethylene plastic refer to 6 mil plastic sheeting or polyethylene bags (or double bags if using 4 mil polyethylene bags), or any other thick plastic material shown to demonstrate at least the equivalent dust contamination performance. Plastic used to contain waste should be capable of completely containing the waste and, after being properly sealed, should remain leak tight with no visible signs of discharge during movement or relocation.

**Polyurethane:** An exceptionally hard and wear-resistant coating (created by the reaction of polyols with a multifunctional isocyanate). Often used to seal wood floors following lead-based paint hazard control work and cleaning.

**Reevaluation:** In lead hazard control work, the combination of a visual assessment and collection of environmental samples performed by a certified risk assessor to determine if a previously implemented lead-based paint hazard control measure is still effective and if the dwelling remains lead-safe.

**Removal:** See **Paint removal**.

**Renovation:** Work that involves construction and/or home or building improvement measures such as window replacement, weatherization, remodeling, and repainting.

**Replacement:** A strategy of abatement that entails the removal of building components coated with lead-based paint (such as windows, doors, and trim) and the installation of new components free of lead-based paint.

**Resident:** A person who lives in a dwelling.

**Risk assessment:** An onsite investigation of a residential dwelling to discover any lead-based paint hazards. Risk assessments include an investigation of the age, history, management, and maintenance of the dwelling, and the number of children under age 6 and women of childbearing age who are residents; a visual assessment; limited environmental sampling (i.e. collection of dust wipe samples, soil samples, and deteriorated paint samples); and preparation of a report identifying acceptable abatement and interim control strategies based on specific conditions.

**Risk assessor:** A certified individual who has completed training with an accredited training program and who has been certified to (1) perform risk assessments, (2) identify acceptable abatement and interim control strategies for reducing identified lead-based paint hazards, (3) perform clearance testing and reevaluations, and (4) document the successful completion of lead-based paint hazard control activities.

**Site:** The land or body of water where a facility is located or an activity is conducted. The site includes adjacent land used in connection with the facility or activity.

**Soil:** See **Bare soil**.

**Spectrum analyzer:** A type of XRF analyzer that provides the operator with a plot of the energy and intensity, or counts of both K and L x-ray spectra, as well as a calculated lead concentration. See also **XRF analyzer**.



**Standard deviation:** A measure of the precision of a reading. The spread of the deviation from the mean. The smaller the standard deviation, the more precise the analysis. The standard deviation is calculated by first obtaining the mean, or the arithmetic average, of all of the readings. A formula is then used to calculate how much the individual values vary from the mean – the standard deviation is the square root of the arithmetic average of the squares of the deviation from the mean. Many hand calculators have an automatic standard deviation function. See also **Mean**.

**Subsample:** A representative portion of a sample. A subsample may be either a field sample or a laboratory sample. A subsample is often combined with other subsamples to produce a composite sample. See also **Composite sample**.

**Substrate:** A surface on which paint, varnish, or other coating has been applied or may be applied. Examples of substrates include wood, plaster, metal, and drywall.

**Substrate effect:** The radiation returned to an XRF analyzer by the paint, substrate, or underlying material, in addition to the radiation returned by any lead present. This radiation, when counted as lead x-rays by an XRF analyzer contributes to substrate equivalent lead (bias). The inspector may have to compensate for this effect when using XRF analyzers. See also **XRF analyzer**.

**Substrate Equivalent Lead (SEL):** The XRF measurement taken on an unpainted surface, used to calculate the corrected lead concentration on a surface by using the following formula: Apparent Lead Concentration-Substrate Equivalent Lead = Corrected Lead Concentration. See also **XRF analyzer**.

**Target housing:** Any residential unit constructed before 1978, except dwellings that do not contain bedrooms or dwellings that were developed specifically for the elderly or persons with disabilities, unless a child younger than 6 resides or is expected to reside in the dwelling. In the case of jurisdictions that banned the sale or use of lead-based paint before 1978, the Secretary of HUD may designate an earlier date for defining target housing.

**Test location:** A specific area on a testing combination where XRF instruments will test for lead-based paint.

**Trained:** Successful completion of a training course in a particular discipline. For lead hazards control work, the training course must be accredited by the EPA or by an EPA-approved State program, pursuant to Title IV of the Toxic Substances Control Act.

**Treatment:** In residential lead-based paint hazard control work, any method designed to control lead-based paint hazards. Treatment includes interim controls, abatement, and removal.

**Trough:** See **Window trough**.

**Windowsill:** See **Interior windowsill**.

**Window trough:** For a typical double-hung window, the portion of the exterior windowsill between the interior windowsill (or stool) and the frame of the storm window. If there is no storm window, the window trough is the area that receives both the upper and lower window sashes when they are both lowered. Sometimes inaccurately called the window "well".

**Worker:** An individual who has completed training in an accredited program to perform lead-based paint hazard control in housing.

**Worksite:** Any interior or exterior area where lead-based paint hazard control work takes place.



**XRF analyzer:** An instrument that determines lead concentration in milligrams per square centimeter (mg/cm<sup>2</sup>) using the principle of x-ray fluorescence (XRF). Two types of field portable XRF analyzers are used – direct readers and spectrum analyzers. For this lead-based paint inspection, the term XRF analyzer only refers to portable instruments manufactured to analyze paint, that have a HUD Performance Characteristic Sheet, and are interpreted in accordance with the Performance Characteristic Sheet. It does not refer here to laboratory-grade units or portable instruments designed to analyze soil.

**XII. Laboratory Results**

**AIHA Laboratory Accreditation Programs, LLC**  
*acknowledges that*  
**Environmental Hazards Services, LLC**  
**7469 Whitepine Rd, Richmond, VA 23237-2261**  
Laboratory ID: LAP-100420

along with all premises from which key activities are performed, as listed above, has fulfilled the requirements of the AIHA Laboratory Accreditation Programs (AIHA LAP), LLC accreditation to the ISO/IEC 17025:2017 international standard, General Requirements for the Competence of Testing and Calibration Laboratories in the following:

**LABORATORY ACCREDITATION PROGRAMS**

- INDUSTRIAL HYGIENE** Accreditation Expires: May 01, 2024
- ENVIRONMENTAL LEAD** Accreditation Expires: May 01, 2024
- ENVIRONMENTAL MICROBIOLOGY** Accreditation Expires: May 01, 2024
- FOOD** Accreditation Expires:
- UNIQUE SCOPES** Accreditation Expires:
- BERYLLIUM FIELD/MOBILE** Accreditation Expires:

Specific Field(s) of Testing (FoT)/Method(s) within each Accreditation Program for which the above named laboratory maintains accreditation is outlined on the attached Scope of Accreditation. Continued accreditation is contingent upon successful on-going compliance with ISO/IEC 17025:2017 and AIHA LAP, LLC requirements. This certificate is not valid without the attached Scope of Accreditation. Please review the AIHA LAP, LLC website ([www.aihaaccreditedlabs.org](http://www.aihaaccreditedlabs.org)) for the most current Scope.

\_\_\_\_\_  
*Cheryl O. Morton*  
Managing Director, AIHA Laboratory Accreditation Programs, LLC

Revision 19.1: 07/28/2021  
Date Issued: 05/01/2022



Environmental Hazards Services, L.L.C.  
 7469 Whitepine Rd  
 Richmond, VA 23237  
 Telephone: 800.347.4010

## Lead in Soil Analysis Report

Report Number: 23-12-00631

**Client:** DK Environmental & Construction Services  
 9007 Paolos Place  
 Kissimmee, FL 34747

**Received Date:** 12/06/2023  
**Analyzed Date:** 12/07/2023  
**Reported Date:** 12/07/2023

**Project/Test Address:** 948 NE 6th St; Ocala, FL 34470

**Collection Date:**

Client Number:  
 201639

# Laboratory Results

Fax Number:

Lab Sample Number	Client Sample Number	Collection Location	Concentration ppm (ug/g)	Narrative ID
23-12-00631-009	S1	COMPOSITE DRIP EDGE A,B,C,D WALL	<21	

**Method:** ASTM E-1979-17/EPA SW846 7000B

Reviewed By Authorized Signatory:

*Melissa Kanode*

Melissa Kanode

QA/QC Clerk

The Reporting Limit (RL) is 10.0 ug Total Pb. All internal quality control requirements associated with this batch were met, unless otherwise noted.

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Results represent the analysis of samples submitted by the client. Unless otherwise noted, samples are reported without a dry weight correction. Sample location, description, area, volume, etc., was provided by the client. If the report does not contain the result for a field blank, it is due to the fact that the client did not include a field blank with their samples. EHS sample results do not reflect blank correction. This report shall not be reproduced except in full, without the written consent of Environmental Hazards Services, L.L.C.

ELLAP Accreditation through AIHA LAP, LLC (100420), NY ELAP #11714.

LEGEND            ug = microgram                            ppm = parts per million  
                           ug/g = micrograms per gram



## Lead Dust Wipe Analysis Report

Environmental Hazards Services, L.L.C.

7469 Whitepine Rd  
Richmond, VA 23237

Telephone: 800.347.4010

Report Number: 23-12-00631

Client: DK Environmental & Construction Services  
9007 Paolos Place  
Kissimmee, FL 34747

Received Date: 12/06/2023  
Analyzed Date: 12/07/2023  
Reported Date: 12/07/2023

Project/Test Address: 948 NE 6th St; Ocala, FL 34470

Collection Date:

Client Number:  
201639

Fax Number:

# Laboratory Results

Lab Sample Number	Client Sample Number	Collection Location	Surface	Total Pb (ug)	Wipe Area (ft <sup>2</sup> )	Concentration (ug/ft <sup>2</sup> )	Narrative ID
23-12-00631-001	1	KITCHEN B WALL CENTER	SL	27.9	0.458	60.8	
23-12-00631-002	2	KITCHEN B WALL CENTER	FL	<5.00	1.00	<5.00	
23-12-00631-003	3	DINING ROOM C WALL CENTER	SL	<5.00	0.458	<11.0	
23-12-00631-004	4	DINING ROOM C WALL CENTER	FL	<5.00	1.00	<5.00	
23-12-00631-005	5	BEDROOM B C WALL RIGHT	SL	27.5	0.458	60.0	
23-12-00631-006	6	BEDROOM B C WALL RIGHT	FL	<5.00	1.00	<5.00	
23-12-00631-007	7	BEDROOM C C WALL LEFT	SL	<5.00	0.458	<11.0	
23-12-00631-008	8	BEDROOM C C WALL LEFT	FL	8.64	1.00	8.64	

Environmental Hazards Services, L.L.C

Client Number: 201639

Report Number: 23-12-00631

Project/Test Address: 948 NE 6th St; Ocala, FL 34470

Lab Sample Number	Client Sample Number	Collection Location	Surface	Total Pb (ug)	Wipe Area (ft <sup>2</sup> )	Concentration (ug/ft <sup>2</sup> )	Narrative ID
-------------------	----------------------	---------------------	---------	---------------	------------------------------	-------------------------------------	--------------

Method: ASTM E-1979-17/EPA SW846 7000B

Accreditation #:

Reviewed By Authorized Signatory: Melissa Kanode

Melissa Kanode

QA/QC Clerk

The Reporting Limit (RL) is 5.00 ug Total Pb. Dust wipe area and results are calculated based on area measurements determined by the client. All internal quality control requirements associated with this batch were met, unless otherwise noted.

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Results represent the analysis of samples submitted by the client. Sample location, description, area, etc., was provided by the client. Results reported above in ug/ft<sup>2</sup> are calculated based on area supplied by the client. If the report does not contain the result for a field blank, it is due to the fact that the client did not include a field blank with their samples. These sample results do not reflect blank correction. This report shall not be reproduced except in full, without the written consent of Environmental Hazards Services, L.L.C.

ELLAP Accreditation through AIHA LAP, LLC (100420), NY ELAP #11714.

Legend	ug = microgram	ug/ft <sup>2</sup> = micrograms per square foot	Pb = lead
	mL = milliliter	ft <sup>2</sup> = square foot	



**DK ENVIRONMENTAL & CONSTRUCTION SERVICES, INC.**

•8786 Sonoma Coast Drive, Winter Garden, FL 34787

•407-614-4572

•814-243-1927

•dkenvironmental@yahoo.com

**Chain of Custody**

**Client:** DK Environmental  
8786 Sonoma Coast Drive  
Winter Garden, FL 34787

**Project Name:** 948 NE 6th St  
Orlando, FL 32803  
**Project No.:** \_\_\_\_\_

**Office Phone:** 407-614-4572  
**Cell Phone:** 814-243-1927  
**Email:** dkenvironmental@yahoo.com

**Contact 1:** Debra Koontz  
**Contact 2:** \_\_\_\_\_  
**Inspector:** \_\_\_\_\_

23-12-00631

**Special Instructions:** \_\_\_\_\_



Due Date:  
12/07/2023  
 (Thursday)  
 AE

**Matrix:**

- Air  Soil  Bulk   
 Water  Paint  Surface Dust/Wipe

**Analysis Method:**

- PCM : NIOSH 7400  
 PCM : OSHA  
 PCM : TWA

- AAS : Lead in Air  
 AAS : Lead in Water  
 AAS : Lead in Paint  
 AAS : Lead Dust/Wipe  
 AAS : Lead in Soil Ghost  
 AAS : TCLP  
 AAS : Metals (Cd, Zn, Cr)

**See Page 2 for Bulk Asbestos Specific Log**

- PLM : Bulk Asbestos EPA 600  
 PLM : Point Counting 198.1  
 PLM : NOB via 198.1 (PLM only)  
 If <1% by PLM, to TEM via 198.4  
 PLM: See page 2 for instructions

**See Page 4 for Mold Specific Log**

- IAQ: I Bioaersol Fungal Spore Trap  
 IAQ: II Bioaersol Fungal Spore Trap  
 IAQ: Tape, Bulk, Misc. Qualitative  
 IAQ: Tape, Bulk, Misc. Quantitative  
 IAQ: Other Culturable ID

- TEM : AHERA  
 TEM : NIOSH 7402  
 TEM : Dust / Wipe  
 TEM : Dust / Microvac  
 TEM : NOB 198.4  
 TEM : Bulk Analysis  
 TEM : Potable Water  
 TEM : Non-Potable Water  
 TEM : Other  
 TEM : Dust : NIOSH 0500  
 TEM : Dust : NIOSH 0600

**Turnaround Time:**

Preliminary Results Requested By: \_\_\_\_\_

Verbals

FAX

Email

- 10 Day  5 Day  3 Day  2 Day  1 Day  12 Hour  6 Hour  RUSH

**Sample Numbers:**

Client #(s): \_\_\_\_\_ Lab #(s): \_\_\_\_\_ Total: \_\_\_\_\_

**Chain of Custody:**

Relinquished (Name / Organization): Debra Koontz  
 Received by (Name): \_\_\_\_\_  
 Sample Login (Name): \_\_\_\_\_  
 Analysis (Name(s)): \_\_\_\_\_  
 QA/QC Review (Name(s)): \_\_\_\_\_  
 Archived/Released: \_\_\_\_\_ QA/QC InterLAB Use: \_\_\_\_\_

Date: 11/29/23 Time: 10:30 am  
 Date: \_\_\_\_\_ Time: \_\_\_\_\_  
 Date: \_\_\_\_\_ Time: \_\_\_\_\_  
 Date: \_\_\_\_\_ Time: \_\_\_\_\_  
 Date: \_\_\_\_\_ Time: \_\_\_\_\_  
 Date: \_\_\_\_\_ Time: \_\_\_\_\_

Rec'd By DBowen 12/6/23 12:14 PM

